

# General Environmental Incident Summary

**Incident:** 3458      **Date/Time Notice:** 9/15/2014      **DEM Incident No:**

**Responsible Party:** RES Americas

**Date Incident:** 9/13/2014      **Time Incident:** 11:00 am      **Duration:**

**County:** Rolette      **Twp:** 163      **Rng:** 69      **Sec:** 13      **Qtr:**

**Lat:** 48.93525      **Long:** -99.53327      **Method:** Interpolation from map

**Location Description:** Entrance of Turbine 75. On 105th St, 1.75 mi east of 52nd Ave.

**Submitted By:** Shabeeb Abdul Khader      **Affiliation:**

**Address:** 10707 52nd Ave

**City:** Rolla      **State:** ND      **Zip:** 58367

## Received By:

**Contact Person:** Shabeeb Abdul Khader  
10707 52nd Ave  
Rolla , ND 58367

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Unknown source

**Description of Released Contaminant:** Diesel

**Volume Spilled:** 3.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

## Cause of Incident:

Approximately 3 gallons of Diesel fuel found on the ground from unknown source on 105th St. (entrance of Turbine 75).

## Risk Evaluation:

None

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

None. Spoil contained in a double waller container.

## Action Taken or Planned:

The spoil was collected using a bobcat, loader and shovel and disposed into the special waste bin in the laydown yard.

## Wastes Disposal Location:

**Agencies Involved:** NRC

## ***Updates***

---

***Date:*** 9/15/2014    ***Status:*** Reviewed - No Action Required

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Facility owners cleaned up the small spill and contained spoil materials which will be sent to an appropriate disposal. No follow-up inspection is needed.